

GUNSMITH CALL REPORTS SUMMARY - JANUARY THROUGH JULY 1974M/1100

- 1) Fore-end Support - 1304
- 2) Action Bars broken - 205
- 3) Barrel Supports - 210
- 4) Interceptor Latch Studs - 55
- 5) Barrel Alignment Studs - 18
- 6) Interceptor Latch Spring - 292
- 7) Rusty Piston, Piston Seals and Magazine Tubes.  
This is a common complaint in the Southern area.
- 8) Gas Cylinder breaking off barrel.

M/3200

Minimal because we asked that all 3200's be returned to the factory the first year.

M/788

- 1) Bolt Handles coming off - 35

M/700

- 1) Rusted Ejectors - 30
- 2) Stock finish and checkering

M/742

- 1) Loose Barrel Extensions. Several  
This is serious because it can lead to a damaged gun.
- 2) Bluing salts weeping
- 3) Occasional hard openers

M/760

- 1) Occasional bluing salts weeping

M/552

- 1) Cracked Bolts

Remaining Models

Miscellaneous