MINUTE #10 - 1975

ſ

(

- ----

a the second

-

83

20:2

ġ

FIREARMS

WOOD PRESS FORMING

MODEL 870, 12-16-20 GAUGE FORE-ENDS

Production reported that a checkering pattern came loose in the profile die. This has been repaired and production is continuing.

The project for an additional set of presses and tooling is circulating for approval.

SHOTGUNS

Shipped

1936

931

 $\| \mathbf{L}_{k}^{(n)} \|_{L^{2}(\mathbb{R}^{N})}$

In

Process

129

23

MODEL 3200 SHOTGUN (Introduction 1973)

Production reported guns returned for modification through May

Shooter's Guns Wholesaler's Guns Guns Credited

(17 - ² About 15 guns per day are being returned. 2 weeks average. Turn-around time is 2 weeks average. a vicini and a single internet. The second se

2115

Received

954

618

The current financial forecast shows a total of 4500 shotguns being returned. Marketing now thinks the total will be higher in the 6,000 to 10,000 range. Since the #3 forecast is being prepared, Marketing was requested to provide a new forecast of returns with quantities by quarters.

Marketing reported that complaint patterns for the improved guns shows nothing significant.

Twenty guns per day are being modified and 54 are being produced to warehouse. This is an annual production of about 12,000 which should go up as returns go down.
