MODEL 3200 MODIFIED GUNS RETURNED THRU 6/16/75

•. .

.

•	•					
		SHOOTER'S	NEW			
		GUN	GUNS	JUST.	N/JUST.	
		1 5				
C.	FAILS TO FIRE	13		12	1	
	ADJUST TRIGGER PULL	11		11		
	STOCK - CRACKED	9		9		
	- TOO HIGH OR TOO LOW	3 1		1	2	
	- HAS CAST OFF		1	2		
	- MARRED	5		5		
	- HAS POOR FINISH	4		4		
	- NOT SATISFIED WITH NEW WOOD	8		7	1	
	- POOR FIT	4		4		
	- TOO STRAIGHT	1		1		
	- HAS POOR FIGURE	2	2	4		
	- WRONG ONE INSTALLED	1		1		
	- CHECK STOCK DIMENSIONS	2		2		
r	- STOCK LOOSE	1		· 1		
	FORE END - CRACKED	14	4	18	. 4 8.0.	
	- MARRED	1	-	1	1955 1978 -	
(- POOR FIT	3		ન હિંદ		
	- POOR MATCH	ī		್ ಕಿಕ್ಷ್ಣಿಸಿ ಮೇ 1 ಕೆ≦		
	BARRELS - HAVE POOR FINISH	<u>,</u>	- 47 h. 	18. . .		1899 - 19 19
	- MARRED		$\mathbb{R}^{\mathbb{N}^{\times \mathbb{N}^{\times 1}}}$	10 - 2.	, and the state of	
			and the Million Salaran	- 1		
	- VENT RIB CROOKED		234 234			
	- SHOT PATTERN QUESTIONED	್ಷ ರಿಭಿತ್ರ - ಹೆಸ್ಟ್ ಎಂಗಿಯ			1	
	GUN MARRED OR DIRTY		ંદે	9 . 5		
	LOOSE ACTION		S.	2		
	BOTTOM TANG POOR FIT	1420 (106)	50°	1		
	FIRING PIN DRAGGING	ing 3 74886		3		
	FIRING PIN HITTING OFF CENTER	1		1		
	LOWER FIRING PIN TROUBLE	1		1		
	BOTTOM EJECTOR LOOSE	· 1		1		
	DOESN'T EVECT	4		4		
	DEFECTIVE SELECTOR	1		l		
	SIGHTS CROOKED	2		2		
	DIFFICULT TO DISASSEMBLE	1		1		
	FRONT SIGHT LOOSE	1		1		
	RECEIVED WITHOUT SIGHTS	l		1		
	GUN DAMAGED IN TRANSIT	1		1		
2 13	FORE-END DAMAGED IN TRANSIT	1		ī		
	NO BOTTOM TANG SCREWS	1		ĩ		
	SHOOTS DOUBLES	1		-	l	
an a	LOOSE BOTTOM BARREL	ī		1	-	
	REBORE BOTTOM BARREL	1		Ŧ	,	
	EXCESSIVE PRESSURE DAMAGE	1			1	
	OPENS HARD	2		2	1	
		2		2		
	SCRATCHES IN CHAMBER	<u> </u>		<u> </u>		
,	TOTAL NUMBER OF COMPLAINTS	130	8	124	14	
C	TOTAL NUMBER OF GUNS	119	8			
-						
	JHS:I					
	6/19/75					
				EXHIE	IT L	

.

. --

EXHIBIT 1