

<u>PERIOD</u>	<u>CODES</u>	<u>PRODUCT SOURCE</u>	<u>100% SALVAGE OR AUDIT WEIGH</u>	<u>QUANTITY WEIGHED</u>	<u>NUMBER PARTL CHARGE DEFEC</u>
October 1972	LX03ED	L-Whse	Salvage Weigh	14 M	1
	LX04ED	"	"	18 M	20
	LX05ED	"	"	18 M	38
	LX06ED	"	"	45 M	None
	LX09ED	"	"	18 M	None
	LX10ED	"	"	22 M	None
	LX11ED	"	"	38 M	None
	LX12ED	"	"	7 M	None
	LX18ED	"	"	7 M	None
	LX19ED	"	"	2 M	None
			Sub Total	217,000	64

December 1972 Based on problem with partial charges encountered in normal surveillance and control testing of product loaded on January 3, 1973, the entire loading of the month of December, 1972, was extensively audited with results as follows:

LX05TD	L-Whse	Audit Weigh	16 M	None
LX06TD	"	"	10 M	"
LX07TD	"	"	7 M	"
LX11TD	"	"	7 M	"
LX14TD	"	"	34 M	"
LX15TD	"	"	6 M	"
LX21TD	"	"	7 M	"
LX29TD	"	"	18 M	"
LX30TD	"	"	16 M	"
		Sub Total	121,000	None
		Total Weighed	634,000	

W. L. Penn
5/7/73

WIL06593