

COMMITTEE ACTION

After discussion, the Subcommittee recommended that the fire control section of our Gunsmith Manual emphasize the function and position of the left connector and disconnecter through word and illustration. More explicit explanations or warnings concerning all of the possible dangers of negligent reversal would only encourage some shooters to intentionally attempt to convert their shotguns to full automatic.

The meeting adjourned at 12:05 p.m.

The next meeting will be held at the call of the Chairman.

*T. J. Sharpe*  
T. J. Sharpe  
Secretary

TJS:jl