

R94-12988

817-666-4381

SEAR LIFT .004

Thick residue in & around trigger
components.

Sealant is missing from sear
engagement screw.

Trigger pull - 4 - 4.5 LBs