

April 6, 1979

XP-100 PISTOL

The Subcommittee has previously decided that XP-100
barrelled actions will not be sold, because we have no control
over the installation of the inertial block which is required
to prevent accidental firing of the weapon if it is jarred.
We are enclosing a notice calling attention to the importance
of the inertial block with pistols returned to owners after
repairs are made. A change in the Owner's Manual is also being
made.

"Silhouette", a publication circulated to silhouette target
shooters, recently carried an advertisement offering barrelled
actions

REDACTED
PRIVILEGED

Legal Department's concerns regarding sales of certain
products.

ATTORNEY-CLIENT—WORK PRODUCT

B. K. Daubenspeck
B. K. Daubenspeck
Secretary

BKD/cas

4/24/79

REDACTED