

September 9, 1980

URGENT!

7mm EXPRESS REMINGTON RECALL

The records of your wholesaler show that you received a quantity of 7mm Express Remington cartridges, our Index Number R7M061.

We have found that a quantity of these cartridges, produced in August, 1979, may produce higher than normal pressures that may damage a firearm. In addition, fired cases may be adversely affected, and should not be reloaded.

We ask that you place an immediate hold on 7mm Express Remington cartridges bearing the following lot numbers, which are printed on the inside end flap of the box:

M02I or M03I or M06I or M07I
or M08I or M09I or M12I.

Any 7mm Express Remington ammunition bearing the above codes should be returned, collect, to:

Remington Arms Company, Inc.
Attn: J. H. Chisnall
939 Barnum Avenue
Bridgeport, Connecticut, 06602.

The quantity returned will be replaced at no charge, so please enclosed a copy of your Federal Firearms License with the return to expedite shipment.

We also ask that you contact all customers who have purchased this ammunition, requesting that they return to you for return to Remington, any loaded rounds or fired shells they have remaining. This, too, will be replaced at no charge.

Many thanks for your cooperation.

Very truly yours,

E. G. Larson
E. G. Larson, Manager
Field and Consumer Services

22:11

WIL06784