

IMPORTANT MESSAGE TO 38 SPECIAL SHOOTERS.

We have recently learned that a quantity of our 38 Special cartridges, manufactured in July 1980, may separate at the case cannellure which could cause part of the case to lodge between the cylinder and the barrel of a revolver. This could damage the gun or cause a malfunction. While the possibility of a personal injury is unlikely, any obstruction in a gun barrel should be considered potentially dangerous.

The ammunition is being recalled at our expense.

To determine whether you have any of the cartridges in question, please look for these markings on the package:

CALIBER: 38 Special

BULLET: 158 grain lead hollow point J.P.

INDEX NUMBER: R38S12

(on outside of end flap)

LOT NUMBERS: P28A and

P29A (on inside of end flap)

If you have cartridges in boxes so marked, do not use them; please return them to us for a prompt, no-charge replacement. Send the ammunition C.O.D. via United Parcel Service (UPS) to:

Remington Arms Co., Inc.

Attention:

Mr. J. H. Chisnall

939 Barnum Avenue

P.O. Box 1939

Bridgeport, CT 06601

Remington • **SMITH**

Remington is a trademark registered in the U.S. Patent & Trademark Office by Remington Arms Company, Inc.

DOCS - 1-80-1-101