

# LIMITED DISTRIBUTION

Minute #5 - 1981

## PRODUCT SAFETY SUBCOMMITTEE MEETING

AUGUST 14, 1981

### PRESENT:

#### Subcommittee

J. P. Glas, Chairman  
P. A. Lewis, Secretary  
R. A. Partnoy  
J. G. Williams

#### Others

J. H. Chisnall  
K. D. Green  
J. E. Preiser  
R. E. Schrader

### 7mm Express Recall

Of the 261,000 rounds involved in the recall, 157,244 cartridges and 3,668 fired cases, amounting to 62%, have been returned to date and product is continuing to be returned. All recall procedures are in place and working well, therefore, the Subcommittee decided to drop this item from the next agenda.

### 38 Special 158 Gr. LHP Recall

Of the 267,000 rounds involved in this recall, 96,342, or 36% have been returned and ammunition is continuing to be returned. Additional advertising is just becoming public.

### 21MM Seismic - Returned Ammunition Evaluation

Additional testing of code N12Y19A was recently conducted. This code was returned by Seismograph Services Corporation, operating out of Clinton, Tennessee. SSC experienced wads and slugs lodged in the barrel and felt they had isolated the problem to this specific code. A total of 200 rounds had been fired after