

returned with the complaint shell indicate that ballistic pressures and case hardnesses are normal. Additional rounds will be pulled down, examined, reloaded and fired to obtain additional information. When this information is obtained the appropriate action will be determined.

270 Win

A review of the complaint history of this product indicates that 40 complaints have been received. The complaint product often exhibits high pressure symptoms, however, there have been no hazardous experiences. 83

The Chairman requested that the Quality Manager develop a test to be conducted by both Production and Research to gain more information about the high pressure symptoms. Competitive ammunition should be evaluated also.

7mm Express in 7mm Magnum Box

A complaint was received through Marketing reporting mispacked product. 7mm Express cartridges were found in one box marked 7mm Rem Mag. The date code on the box was R14H (1/14/81). Examination of ten cases of the same code at the dealer's warehouse did not reveal any additional improperly packed product. 16,300 rounds of 7mm Rem Mag were packed on 1/14/81 and no 7mm Express was packed on that day. It was felt that the the mispack may have been an isolated instance, and possibly the result of a dealer mix.