


EXHIBIT "A"

NEWS RELEASE

Remington.  REMINGTON ARMS COMPANY, INC. • PUBLIC RELATIONS • BRIDGEPORT, CONNECTICUT 06602

FOR RELEASE IMMEDIATELY

Bridgeport, Conn., October 13 -- Remington Arms Company, Inc., today announced the recall of defective 7mm Express Remington cartridges which were manufactured in September and October of 1979.

Remington said the defective cartridges may produce higher than normal pressures which could damage some firearms, and which, under some circumstances might cause personal injury. The company also recommended that fired cases from the ammunition not be reloaded because of possible adverse effects.

The 7mm Express Remington cartridges covered by the recall have the following markings on the packages:

Culiber: 7mm Express Remington
Bullet: 150 gr. Pointed Soft Point "Core Lokt"
Index No.: R7M061 (on outside of end flap)
Lot Nos.: M20F through M29F and
M010 through M110
(on inside of end flap).

Remington said it recalled several other lots of 7mm Express Remington cartridges in September 1980 because of a similar problem. The lots, which were manufactured in August 1979, were: M021, M031, M061, M071, M081, M091, and M131.

The company said it is informing wholesalers and dealers to withhold from sale all 7mm Express Remington cartridges in their inventories which bear lot numbers from both recalls. Remington representatives will make arrangements for return of the cartridges.

WIL06839