

	1	2	3	4	5	6
9/28/81						
1	870 CT	4rd.	1rd.			
2	V 684939V	Sam 1512700R	54gr.	receiver failure		
3	split receiver	8700psi	710X	case failure		
4			54300psi	blew off carrier		
5						
6	870 CT	3rd.	1rd.	receiver wrinkled		
7	V 734624V	Sam 1	49gr. 200X	case failed		
8	split receiver	9210psi	401200psi	carrier bent		
9						
10	9/29/81					
11	Std 870 CT	5rd.	1rd.	receiver wrinkled	83	
12	V 724208V	Sam 1	49gr. 200X	blew off carrier		
13	split receiver	9500psi	49600psi	case failed		
14						
15						
16	870 CT	5rd.	1rd.	receiver wrinkled		
	671331	Sam 1	48gr. 200X	case failed		
18	split receiver	8700psi	35200psi			
19						
20						
21	Std 870 CT	1rd. Sam 1	1rd.	1rd.	failed case	
22	744800	9470psi	36gr. 200X	39gr. 200X		
23	split receiver		27300psi	30200		
24						
25						
26	870 CT	1rd.	1rd.	1rd.	failed case	
27	734642	Sam 1	36gr. 200X	39gr. 200X		
28	split receiver	7900psi	27300psi	31300psi		
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						