

Test Summary  
February 25, 1983  
Page 5

Held in Lonoke	223.0M
Held in Bridgeport	75.5M
	-----
Total	298.5M
In Field	166.0M

I. Conclusions

- a. High pressure problem is apparently limited to the 6mm Rem 80 grain load.
- b. 303 British and 8mm Mauser have not been affected.
- c. Problem apparently started with HRP powder Lot 3.
- d. Pressures with the powder dry and/or hot stay below proof load limits.

TEB:pc  
2/25/83

CONFIDENTIAL 83

WIL06883