

6mm REMINGTON 80 GRAIN, HIGH PRESSURE

Further monitoring of warehouse product in question (Lot #3) indicates that all rounds tested produced lower than nominal SAAMI proof load pressures (709 CUPS).

WARNING ROLLMARK

At the February 2, 1982 Product Safety Subcommittee Meeting, it was decided to rollmark a warning on Remington barrels directing the owner to read the Instruction Book for safe operation. Marketing questions whether such a rollmark should be placed on barrels manufactured for custom guns. After discussion, the Subcommittee decided that since Remington can contact all custom gun purchasers directly, Marketing should develop a procedure to communicate with custom gun purchasers concerning the safe operation of the firearm without having to rollmark a warning on the custom gun barrels.

MODEL SEVEN RECALL

Known purchasers of the Model Seven are currently being contacted by letter. To date, 1,300 new fire controls were installed.

J. H. Chambers
J. H. CHAMBERS
SECRETARY

JHC/kam
0008c

WIL06891