

IMPORTANT MESSAGE TO LAW ENFORCEMENT AGENCIES

Certain lots of Remington 38 special and 9mm cartridges manufactured in May and June 1985, may have insensitive primers which could result in a failure to fire. Therefore, this ammunition is being recalled at our expense.

Look for the following product specifications on the end flap of the box:

38 Special (+P) 95 Grain SEMI JACKETED HOLLOW PT.	R38S1	38 Special (+P) 110 GR. SEMI JACKETED HOLLOW PT.	R38S10
38 Special (+P) 125 GR SEMI JACKETED HOLLOW POINT	R38S2	38 Special (+P) 158 GR. LEAD HOLLOW PT.	R38S12
38 Special 158 GRAIN LEAD	R38S5	9MM Luger 115 GR. JKTED. HOLLOW PT.	R9mm1
38 Special (+P) 158 GR. Lead	R38S8	9MM Luger 124 GR. Metal Case	R9mm2

If you have any of these cartridges, look for the identification code printed on the inside end flap. Only products with identification codes beginning with the letter "C" and with a "T" or an "H" as the fourth character are being recalled. Example - C03T132441 or C03H162132.

If you have any of the recalled cartridges, do not use them. For prompt replacement at no charge, please call collect:

Bill Smith
Remington Arms Company, Inc.
Remington Road
Lonoke, AR 72086

Telephone (501) 676-3161 Ext. 840