

Remington Arms Co. Inc
Arms Service Div.
14 Hoeft Ave
ILION NY. 13357

11/17/40

Remington Mod 700 BDL
Ser # A6588602 is being
returned for repair.

The rifle has discharged
on several occasions when
the safety has been moved
from S to F even though
my finger was off the
trigger. I have not tried
to make any alterations to
the trigger pull since I
have owned the rifle or even
had the action out of the
stock.

This condition causes me
great concern since an
accidental discharge could