

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDERING

DATE RECEIVED 10/29/92 DATE ORDERED 10/29/92 DATE CODE 10/29/92 SERIAL NUMBER 10/29/92 MODEL AND GRADE 700 THUNDER

ORDER 700 THUNDER

ACCESSORIES 10/29/92

FROM:

BURNS, JOHNNY
3336 COUNTRY CLUB DR
CHARLOTTE NC 28205

SHIP TO:

BURNS, JOHNNY
3336 COUNTRY CLUB DR
CHARLOTTE NC 28205

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

J. P. FOSTER
5018 CARILION DR.
CHARLOTTE, NC 28226

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☒ LIKE
NEW☐

SLIGHTLY WORN

☐

VERY WORN

☐

MISUSED

☐

MARRED

CUSTOMER'S REQUEST

"GUN FIRED WHEN SAFETY WAS PUSHED OFF"

MAIN FAULT

Trigger assembly rusted from unknown source. Internal
parts not moving properly.Note: barrel rusty at muzzle point location and, rear guard assembly rusty.
Appears rifle was not at some time & not properly maintained.

PARTS

Per J. Foster (Sales Rep) instructions,
rifle to be returned shipped to him
via U.P.S. NEXT DAYReplace Trigger assembly at no charge
as gesture of good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 7/90