

ROBERT F. BUTLER

LAWYER  
Nevada and California

1675 Lakeside Drive  
Reno, Nevada 89509-3408

Telephone  
(702) 322-5989

RECEIVED

FFR 2 3 1988

CONSUMER SERVICE

February 18, 1988

Remington Arms Company  
1007 Market Street  
Wilmington, Delaware 19898

Attention: Product Information

Gentlemen:

I purchased a Remington Model 700 BDL some 20 years ago. I have never had a problem with it until my last hunt. After subjecting the rifle in its scabbard to a tremendous jolt (when my horse walked into a tree), it discharged when a round was chambered.

I am writing for 2 reasons:

- (a) I am scared to death of the rifle now, and
- (b) I need to know what caused it.

Can you help?.

Sincerely,

Robert F. Butler  
Robert F. Butler

:si

Per phone call 3/4/88 - Butler is  
sending rifle to Arms Service for inspection  
Jas.