

4-8-94

DEAR SIR,

IN MY ORIGINAL LETTER TO REMINGTON, I
STATED THAT THIS RIFLE HAS A TENDENCY TO
ACCIDENTLY DISCHARGE ON OCCASION WHEN TAKING
OFF THE SAFETY.

THIS GUN IS USED VERY LITTLE, MOSTLY IN
LATE FALL AND WINTER WHILE PREDATOR CALLING.
THE ACCIDENTAL DISCHARGES SEEM TO OCCUR
WHEN THE RIFLE HAS SAT DORMANT FOR LONG PERIODS
OF TIME AND ALWAYS WITH THE VERY FIRST
ROUND CHAMBERED.

I HAVE JUST RECENTLY TAKEN THE BLUING
OFF THIS RIFLE BECAUSE IT WAS BADLY WORN. I
FOUND OUT THAT IT IS STAINLESS AND CAN'T GET IT
REBLUED LOCALLY.

Dennis Button
13860 Dullette Road
Allison, N.Y. 14411

MODEL 700 17 CAL.
SERIAL No 6445063

OFFICE COPY		DATE	DATE	PATTERN
		DATE	DATE	DATE
RD6925 REV. 1/84				