

Remington

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS AMMUNITION TARGETS TRAPS

ILION, NEW YORK 13357

December 7, 1981

Active Grinding, Inc.
Attn: Mr. Joe Latta, Owner
882 South Rose Place
Anaheim, California 92806

Dear Mr. Latta:

Your letter of November 11, 1981 to our Bridgeport, Connecticut facility, regarding the difficulty you encountered with your Model 700 7mm Rem. Mag. caliber rifle firing when the safety was moved from the "safe" to the "fire" position, has been received and forwarded to this office for reply.

We were indeed sorry to learn of your having a problem of this nature, as it is not characteristic of the Model 700 rifle.

Generally, the type of incident you have described does not result from a problem in the rifle, but from pressure being inadvertently applied to the trigger. However, inasmuch as this problem has occurred on three (3) separate occasions, we do request the rifle be returned to us for examination.

Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Company, Inc.
Arms Service Division
Ilion, New York 13357

If, upon receipt, the rifle is found to be factory faulty, any necessary repairs or replacements will be made on a no-charge basis.

Thank you for your letter and for having afforded us this opportunity to be of service.

Sincerely,

J.A. Stekl, Supervisor
Firearms Product Service

ASL:pp

OCT 8 1982