

RECEIVING AND ESTIMATING REPORT ✓

TIAL		CUSTOMER ORDER NO.		COMMENTS			
JM							
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
1/18/91	01/28/91	AZ 3-75	6846400	700 30-06 BDL		R 91-02777	
ACCESSORIES		W/STUDS		SCOPE BASE			

OM: CAMPBELL, WILLIAM L
HC 66 BOX 266B
FERRIDAY LA 71334

SHIP TO: CAMPBELL, WILLIAM L
HC 66 BOX 266B
FERRIDAY LA 71334

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					2-8-91	UPS

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST

Gun fired when Bolt was closed.

TS N FAULT *Trigger assembly contaminated with sticky, gummy residue. Internal trigger parts are gummed and not moving properly. Semi-auto gun sticks to cycle plate of trigger housing; Bolt release is sticking and not operating properly. Outside of trigger assembly and return of action wet with excessive oil(?)*

Send quotation to clean present trigger assembly, if possible. If not possible, we can install a new trigger assembly at ± normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>R.B.B.</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90