

April 27, 1994

Remington Arms Company  
Arms Service Division  
14 Hoefler Avenue  
Ilion, NY 13357


Dear Sir;

I recently purchased, at an auction, the enclosed Model 700 BDL, serial number A6430321, .308 caliber bolt action rifle and upon cleaning I discovered the trigger assembly was damaged. I request you install a new trigger housing assembly and also inspect/replace the sear because when I close the bolt with the safety off, the firing pin will sometimes go forward.

I authorize repair and shipping costs to be charged to my VISA, account number:

4800 1206 3200 4164 which expires on 5/31/95.

Sincerely,



John M. Campoli  
1753 Legare Lane  
Virginia Beach, VA 23464  
Day Time Phone: 804-486-5895 or 703-663-8594  
Night Phone: 804-479-1460