

Dear Sir:

Would you please check the Remington
700 AAL Serial# A6480720, it discharged
after the bolt was being closed.

Thank You
Rod Caney

ORDER
R91-23431

STEKO

ADL

TERS SUPPLY
WINING RD
NY
13662

DATE 2/1/79	VIA UPS
REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

INSPECT

1. *Wires*

2.

3.

4.

5.

*possibly, however
it has been a great
service - With
Kinzer - Travel*

*and re-seal
by, or, if owner
will a new
original cost,
with it, it will
be in the right*

REPAIRMAN <i>NR</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91