

ADD. - 705
SR No. 4250346
RECD. 1-4-83
RECEIVED BY L. H. L. L.
INDEXED ✓

R# 01224
PI 1:
MFD. 7-69

COMMENTS:

7-18-83

DISASSEMBLING THE GUN TO SUBASSEMBLIES, THE FOLLOWING OBSERVATION
MADE:

(1) THERE WAS A BRIGHT POLISHED LIPSET ON THE FRONT PORTION EDGE
OF THE BOLT PLUG APPROXIMATELY $\frac{1}{2}$ " RIGHT OF THE FRONT AN
HEAD SLOT CENTER LINE.

(2) THE ENGAGEMENT SURFACE OF THE BOLT AN HEAD APPEARED TO BE
RELATIVELY ROUGH.

(3) THERE WAS QUITE A LOT OF DEBRIS (OIL + DIRT) ON AND
AROUND THE TRIGGER HANGING ASSEMBLY.

(4) SOME COLLING WAS OBSERVED ON THE LEFT BEAR OF THE BOLT
WIRE AT THE RECEIVED TANK.

TRIGGER HANGING ASSEMBLY WAS REMOVED FROM THE PARCELED ACTION/
THE FOLLOWING OBSERVATIONS WERE MADE:

(5) THE BOLT LOCK APPEARED TO HAVE A RELATIVELY LARGE RADIUS
ON TOP.

(6) A FINE GRAY WAS EVIDENT WITHIN THE TRIG. HANGING ASSEMBLY
(LOOKED LIKE OIL + DIRT).

(7) ALL SCREWS WERE TIGHTLY SEALED.

TRIGGER HANGING ASSEMBLY WAS DISASSEMBLED AND THE FOLLOWING OBSERVATION
MADE:

(8) THERE WAS A SMALL AMOUNT OF CLEARANCE BETWEEN THE TOP OF
THE TRIGGER AND THE BACK OF THE CONNECTOR WHEN THE
CONNECTOR WAS SEATED DOWNWARD ON THE TRIGGER. OK