

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
FPS		75325					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
05/08/91	05/08/91	KY 5-74	6741954	700 308 WIN BDL		R 91-1055	
ACCESSORIES		W/STUDS		L/SIGHTS			

FROM: CHARLIES SPTG GOODS
7401 H MENAUL N E
ALBUQUERQUE NM 87110

SHIP TO: CHARLIES SPTG GOODS
7401 H MENAUL N E
ALBUQUERQUE NM 87110

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	---------

EPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST "Customer said fired while on safe - when he bumped gun."

MAIN FAULT Cannot duplicate complaint, however, trigger assembly has been completely mis-adjusted outside of factory - foreign sealant on all adjusting screws: 1) trigger pull felt over 23, # 2) insufficient rear engagement 3) excessive over-travel. See left O.L.C. 00811

ARTS	Since rear engagement has been altered outside of factory, send quote for new trigger assembly at \$200.00 as gesture of good will.				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90