



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

July 26, 1988

Mr. William L. Chesley
P.O. Box 124
Cold Bay, Alaska 99571

Dear Mr. Chesley:

Examination has been completed on the Model 700 ADL 30-06 caliber rifle, serial number B6662291, that you returned to us because "on two separate occasions, it accidentally fired as the safety switch was being changed from "s" to "f" with a round in the chamber."

The returned firearm, which was produced in December of 1984, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be good, and in going over the individual parts we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction you reported. All tolerances and dimensions were found to be normal. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made to the trigger adjustments outside our factory. Trigger pull was measured to be five (5) pounds, and sear lift with the safety in the "on-safe" position was well within specifications at .0115".