

I have also included two (2) once fired cases that show you another problem I am having. It seems that with a moderate reload:- 47.0 Grains of H380 powder, A Nosler 150 Gr. Ballistic Tip bullet and a Federal 210 Match primer the primers will pop out of the case. (See enclosed rifle cases) My thinking is that there could possibly be a headspace problem?

I would appreciate very much if you would give this gun a complete inspection and correct any problem that there might be. I feel that possibly there might still be a problem in the Trigger Assembly of the Model Seven rifle that should be corrected.

Your prompt and courteous attention to this letter will be appreciated.

Sincerely
William Cinti
P.O. Box 385
Claridge, Pa. 15623