

-2-

Should you need a box for shipping purposes, please call 1-800-634-2459.

If your rifle has had its trigger assembly replaced with a non-Remington trigger assembly since being serviced by Remington, or has been sold by you, please provide the information requested on the form enclosed. Then, return that form to Remington, Dept. RP, using the postage paid envelope provided.

We apologize for any inconvenience this may cause you.

Please remember that this trigger assembly replacement program applies only to a limited number of recent Model 700 series guns (Models 700, Seven, Sportsman 78 and 40X series) and not to any other Remington gun models.

However, regardless of your rifle's age, it did receive an affected trigger assembly between July 29 - December 11, 1987. Therefore, it is essential that your rifle be returned for a new trigger assembly as soon as possible. In the meantime, you should not load or shoot the firearm.

If you have any questions about this trigger assembly replacement program, you may call toll free at the above 800 number.

Sincerely,



R.H. Potter  
Supervisor  
Product Service

RHP:tpg  
encl.

*Remington Arms Company, Inc.*