

RRR-114

P.I. YES GUN EXAMINATION REPORT NUMBER: 485 MODEL: 705
 GENERAL CONDITION: FAIR S#: 17327
 OUTSIDE WORK: STOOD 2000 DATE: 7-1-81
 FIRED AMMO TYPE: REM PETERS FROM: DEMMS CLARK
 & CONDITION: 7 SPENT CLIPS 125-705-12
 PROOF: L DISP.: 9 TEST: 87 COSE: 54471
 HEADING: OK GA./CAL.: 222 REM
 BREACH OPENING: OK CHECKED BY: M-H 1904
 RECOIL SHOULDERS: OK APPROVED: PO 7/2/81
 CHAMBER: OK APPROVED: PO 7/2/81
 TEST: OK APPROVED: PO 7/2/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: PO 7/2/81
SMALL MARKS ON STOCK JERKED OUT SUBST. WORK!
BOLT PLUG DAMAGED.

COMPLAINT: NO INFORMATION

INCIDENT: _____

COMMENTS: Trigger adjustment screw set out of specification.
Trigger adjustment & overtravel screws - Sealant missing
indicating adjustment outside of factory. Trigger pull
2# out of Remington Specs 3# to 5#.