

INITIAL JMJ	CUSTOMER ORDER NO.		COMMENTS	
DATE RECEIVED 1/31/91	DATE OPENED 02/07/91	DATE CODE AR 3-68	SERIAL NUMBER 335193	MODEL AND GRADE 700 30-06 BDL
ACCESSORIES W/STUDS				ORDER R 91-0389

FROM:

COGNEVICH, LOUIS M, JR
568 W MARLIN CT
GRETN

LA 70056

SHIP TO:

COGNEVICH, LOUIS M, JR
568 W MARLIN CT
GRETN

LA
70056

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	-----------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION:

☐ NEW☒ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

TOMER'S REQUEST

"If the trigger is pulled prior to releasing the safety, when the safety is released the gun will discharge."

4 FAULT

Complaint could be implicated. Trigger assembly has been adjusted inside factory. Additionally, trigger parts were coated with a waxy type substance which appeared like solidified lubricant. This combination resulted in the malfunction noted.

5

Rifle was replaced by Contact Service, during delay in handling.

Per phone call to customer 3/28/91, replace trigger assembly at no charge, as a gesture of good will.

Do not charge handling or return shipping

REPAIRMAN LEW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

STCKL

RD0925 REV 7.90