12UL-105

UUN 2 8 1984 J. A. STEKL

May 24, 1984

-2-

the bolt while the safety is in the "on safe" position, at no-charge, to insure that your faith in the rifle is restored, or, the rifle can be returned to you in the same condition as received. We will await your decision and reply.

We apologize for the delay in completing examination of your firearm, and thank you for having afforded us the opportunity to be of service to you.

Sincerely,

Stekl, Supervisor Product Service

JAS: tpp Dear Mr Steke Thank you for taking the time to check my rifle out. I would feel better if you re-newed that part, but most of all, I feel that the bolt caused this incident Thank you again for everything, and I will be looking for my rifle as soon possible