

Please find enclosed customized XP-100 in IHMSA TMM International.

All inletting of the receiver and milled portion of the bolt was done at my request in order to meet weight specifications.

My complaint is the shoddy work and craftsmanship and the treatment I received. The bolt has been backed to the point its unacceptable. The parkerized finish is sloppy and they even failed to buff the barrel before it was applied.

After numerous trips and ~~and~~ very vocal complaints, I've received a "cave less" attitude from him. I'm referring to your repair station Darnall Gun Works

Bloomington, Ill.

Unauthorized welding and grinding resulted in failure (breakage) of the bolt handle. Also the original configuration was altered without my knowledge. Darnall tried to "stick" weld it but made matter worse in function and appearance and has failed miserably. The treatment and service I received has upset me tremendously.

In desperation I finally called Remington and suggested I send the entire pistol for evaluation.

Since the shooting season is here for IHMSA I would greatly appreciate the early