

*Customer Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDL VAR.GENERAL CONDITION: NEWR #: 12943OUTSIDE WORK: NODATE: 6-29-71FROM: H.P. COXMEER HIGH SCHOOL
ARLEY, ALABAMAFIRED AMMO TYPE: -GUN #: 6403250

& CONDITION: _____

ASSEMBLER 90PROOF: R.E.P.-C INSP.: 9 TEST: 49CODE: LU = 2/71HEADING: O.K.GR./CAL.: 223BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: 40 ROUNDS, REMINGTON

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR AND TRIGGER CONNECTOR COENERS BROKEN OFF,
ENGAGEMENT P.015 (.005 UNDER MIN.) FIRING PIN POINT
RADIUS TOO LARGE.

COMPLAINT: FIRE ON CLOSING, FIRED WHEN SAFE WAS PUSHED
OFF, PIERCED PRIMERS.

INCIDENT: FOLLOWED DOWN.

COMMENTS: THE PRIMER PIERCING WAS NOT DUPLICATED IN TEST-
ING. IT MAY HAVE SPEEDED UP THE CONNECTOR - SEAR
BREAK-DOWN