

STEVEN CRUDUP  
419 DODSON LAKE DR.  
ARLINGTON, TX 76012  
(817) 265-6731

REMINGTON ARMS CO.  
PRODUCT SERVICE  
14 HOEFLER AVENUE  
ILION, NY 13357

DECEMBER 1, 1992

ATTN: JIM STEKL

DEAR JIM,

AS PER OUR TELEPHONE CONVERSATION I AM SENDING YOU MY  
REMINGTON 700 BDL 30.06 RIFLE. AS I EXPLAINED THE GUN  
DISCHARGED AS I MOVED THE SAFETY FROM SAFE TO FIRE. I  
WAS ATTEMPTING TO UNLOAD THE RIFLE. WHEN THE GUN FIRED  
THE BULLET HIT MY 1988 FORD PICKUP AND WENT THROUGH THE  
INTERIOR FLOORBOARD AND PIERCED A GAS LINE.

I TOOK THE GUN TO ALPINE GUNSMITH, IN FT. WORTH, TX.,  
AND HE DRY FIRED THE GUN 2 OF 5 TRIES SIMULATING REMOVING  
THE GUN FROM SAFE TO FIRE. HE CLEANED THE GUN COMPLETELY  
AND RETURNED IT TO ME.

I HAVE LOST ALL CONFIDENCE IN THE RIFLE AND NOT HUNTED WITH  
IT SINCE. I NOW UNDERSTAND REMINGTON HAS MODIFIED THE SAFE  
MECHANISM IN ORDER TO SOLVE THIS PROBLEM.

I WOULD LIKE TO BE ABLE TO TRUST THIS RIFLE ONCE AGAIN,  
AND HUNT WITH IT. IF YOU WOULD PLEASE IDENTIFY THE PROBLEM,  
FIX THE PROBLEM AND UPGRADE THE RIFLE TO CURRENT TECHNOLOGY.  
THANK YOU FOR BEING SO HELPFUL,

STEVEN CRUDUP