

Custom Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: NEW R #: 26143
 OUTSIDE WORK: NO DATE: 11-12-70
 FROM: DAKIN SPTS. GDS. Co.
 FIRED AMMO TYPE: - BANGOR, MAINE
 & CONDITION: _____ GUN #: 6219140
 PROOF: R.E.P. INSP.: _____ TEST: ASSEMBLER 41 CODE: LS-2/69
 HEADING: O.K. GA/CAL.: 3006
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: - APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.COMPLAINT: "WILL NOT STAY COCKED"INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN CONNECTOR MAKES RETRACTION
UNDER SEAR UNCONTROLLABLE. THE CONNECTOR
FAILING TO RETRACT CAUSES FOLLOW DOWN.