

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER R 94-00479

INITIAL FJS	CUSTOMER ORDER NO.		DATE RECEIVED 01/03/94		DATE OPENED 01/05/94	DATE CODE KN 5-93	SERIAL NUMBER S6233971	NEW SERIAL NUMBER	MODEL AND GRADE 700 338 WIN	MAG/SS/BDL
ACCESSORIES W/STUDS										

FROM:

DALLEY, BILL
4325 WEST 14TH ST. ROAD
GREELEY CO 80634

SHIP TO:

DALLEY, BILL
4325 WEST 14TH ST. ROAD
GREELEY CO 80634

CUST NO: 089968 C.O.D. L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059015	WRITE <input type="checkbox"/>	FROM DATE	ESTIMATED 2-10-94	VIA UPS
GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED			REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	"	*P1				
TRIGGER GROUP	Will Not Lock				F1	F1
BOLT ASSY.					F2	F2
BARREL ASSY.					F3	F3
REC. ASSY.					F4	F4
WOOD			G1	G2	L5	L5
METAL			G2			

MAIN FAULT

Upon receipt, unable to duplicate customer concern. Examination revealed that at 3 trigger adjustment screws were too tight. Called customer, he stated that the screws loosened before he was given the adjustment all in an attempt to correct.

PARTS

TP - 2 1/4 lbs removed below min. spec.
SL - .014

COMMENTS

Agreed to replace trigger group and that rifle is given to good unit.
Rifman - mfg 5/93

REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/9