

12-22-93

DEAR SIR:

I PURCHASED THE ENCLOSED Rem 700
SG233971 LAST FALL JUST BEFORE
ELK SEASON. I GOT IT HOME AND
CLEANED IT. WHEN WORKING THE BOLT
SEVERAL TIMES IT DID NOT COCK.
I THOUGHT THAT JUST MAYBE I HIT
THE TRIGGER AND LET IT DOWN. I
WORKED THE BOLT CAREFULLY AB
20 TIMES + THE STRIKER FELL AC
THINKING THAT IT MIGHT BE HANGI
IN THE STOCK, I REMOVED IT. THE
RIFLE FAILED TO COCK ON SEVERA
OCCASIONS. I TOOK IT TO A LOC
GUNSMITH, HE CHECKED IT AND IT
FINALLY DID IT FOR HIM. HE WOK
ON IT FOR A COUPLE OF DAYS AND
UP WITHOUT SUCCESS. THIS RIFLE
NEVER BEEN FIRED AND I'M AFRAID
OF IT. IF IT SHOULD LET DOWN
A LIVE PRIMER IT MIGHT FIRE.
THE EASIEST WAY TO GET IT TO MALF
IS TO HOLD THE TRIGGER AND LET T
BOLT DOWN. BY RAISING AND THEN LOO
THE BOLT HANDLE IT SHOULD COCK. S
TIMES IT DOES AND SOMETIMES IT DON'T
BILL DALLEY TELEPHONE 303-356-0011
4325 WEST 14TH ST. ROAD, GREELEY, COLORADO