

RECEIVING AND ESTIMATING REPORT ✓

INITIAL PS		CUSTOMER ORDER NO. 5816		COMMENTS	
DATE RECEIVED 11/21/91	DATE OPENED 01/29/91	DATE CODE CC 4-82	SERIAL NUMBER B6382158	MODEL AND GRADE 700 25-06 BDL	ORDER R 91-0290
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS	

FROM:	SHIP TO:
DANNYS PAWN & SPORTING 300 S BROADWAY MCALLEN TX 78501	DANNYS PAWN & SPORTING 300 S BROADWAY MCALLEN TX 78501

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 2-6	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *rifle sometimes fires when bolt is closed*

MAIN FAULT *Cannot duplicate complaint. However, trigger assembly contaminated with a sticky substance; internal trigger parts are not moving freely. In addition, trigger assembly has been improperly adjusted outside factory - insufficient over-travel & insufficient rear engagement. Trigger pull O.K. at 4 pounds - rear lift O.K. at 0.12". Rifle has not been properly maintained.*

Send repair quote for new trigger assembly but I'll proceed with as gesture of good-will.

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 7/90