

P.I. _____ GUN EXAMINATION REPORT NUMBER: _____ MODEL: 702 BDL
 GENERAL CONDITION: GOOD - WELL USED R #: 06337
 OUTSIDE WORK: STICK SHORTENED, PREVIOUS GLASS-
BEADED, SIGHTS REMOVED DATE: JUNE 29, 1963
 FIRED AMMO TYPE: UNKNOWN FROM: HARTWELL GARMENT CO.
 HARTWELL, GA. 30643
 & CONDITION: _____ GUN #: 2664722R
 PROOF: ✓ INSP.: ✓ TEST: ✓ CODE: WDA-78
 HEADING: _____ GA./CAL.: 7MM REM MAG
 BREACH OPENING: _____ CHECKED BY: RONALD JACKSON
 RECOIL SHOULDERS: _____ APPROVED: CH 6/20/83
 CHAMBER: _____ APPROVED: 6/20/83
 TEST: _____ APPROVED: ✓
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

EXAMINATION OF THE FIREARM SHOWED NO DIMENSIONAL DEFECTS ON
 ANY OF THE PARTS.

COMPLAINT: GUN FIRED UPON RELEASING THE SAFETY, AS PER THE CUSTOMER,
 CAUSING DAMAGE TO A PICK UP TRUCK
 INCIDENT: _____

COMMENTS: COLD STORAGE AND ADDITIONAL TESTS CONDUCTED COULD NOT DUPLICATE
 THE INCIDENT. HOWEVER, SEVERAL STEEL CHIPS WERE FOUND IN THE TRIGGER
 HOUSING THAT COULD HAVE POSSIBLY BEEN FROM THE FACTORY. BASED ON
 THESE FINDINGS, THE POSSIBILITY EXISTED THAT A CHIP COULD HAVE CAUSED
 THE INCIDENT.