

11-23-88

Repair Dept. Supervisor,

Enclosed please find my Remington 700 BDL, 30-06 rifle, Serial #A6833899. I purchased it from Humm's Sporting Goods in Paramus N.Y. several years ago. Going back to 1985 I was hunting deer in Pennsylvania and when I shot at a deer the weapon did not go off. It appeared that it did not release the firing pin. After cleaning the weapon I dry fired it & then fired live rounds through it & it fired well. I take very good care of my weapons & do not adjust any of the mechanisms. The very next deer season in 1986 the weapon did not fire at 41 different deer the same day. The weather was very cold, but dry. I use very little Rem oil on it, not to let it build up. I did not hunt in 1987 but used the weapon regularly for varmint hunting. In warm weather there's no problem. Before 1988 New York Deer season (11/22/88 exact date) I brought the weapon to an authorized gunsmith & he cleaned & checked the gun over & stated that he could not find anything wrong with it. On 11-22-88 I went to N.Y. to