

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-03195

INITIAL CUSTOMER ORDER NO.

JJM	DATE RECEIVED 01/20/92	DATE OPENED 01/27/92	DATE CODE RF 11-85	SERIAL NUMBER R6756272	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 MTN
ACCESSORIES W/STUDS						

FROM:	SHIP TO:
DELOACH, JOEL K RT 1 BOX 101 HAMPTON TN 37658	DELOACH, JOEL K RT 1 BOX 101 HAMPTON TN 37658

CUST NO: 056979 C.O.D.

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 2-18-92	VIA UPS
CONDITION						REPAIR CHARGE
NEW						EXCISE
SLIGHTLY WORN						TAX
WORN						INSURANCE
VERY WORN						UPS
UNREPAIRABLE						PARCEL POST
					TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
LT ASSY.		B3				F2
RR REL ASSY.		B4		D1	E3	F3
C. ASSY.				D2		F4
WOD			C1	D3	E5	F5
ITAL			C2			

NO FAULT
Trigger assembly is contaminated with a gunning studing
substance - internal trigger parts not moving freely nor properly
can - Safety can be studied to add photo of trigger assembly
if has not been properly maintained
vign pull 5 Pounds, read left 0.012"

ITS	COMMENTS Offer to clean present trigger assembly, if possible. If not possible, offer replacement assembly at 2 regular cost, as a gesture of good-will.				
REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

076026 REV. R101