

# BARBER - Kinzer RECEIVING AND ESTIMATING REPORT

|                            |                         |                      |                           |                                  |  |                 |  |
|----------------------------|-------------------------|----------------------|---------------------------|----------------------------------|--|-----------------|--|
| INITIAL<br>JJM             |                         | CUSTOMER ORDER NO.   |                           | COMMENTS                         |  |                 |  |
| DATE RECEIVED<br>09/26/90  | DATE OPENED<br>10/05/90 | DATE CODE<br>AA 3-80 | SERIAL NUMBER<br>A3200135 | MODEL AND GRADE<br>700 30-06 BDL |  | ORDER<br>90-258 |  |
| ACCESSORIES<br>SLING STRAP |                         | W/STUDS              |                           | W/SWIVELS                        |  | SCOPE BASE      |  |
| L/REAR SIGHT               |                         |                      |                           |                                  |  |                 |  |

FROM:

DENNIS COMPANY  
115 S 4TH ST  
ELMA WA 98541

SHIP TO:

DENNIS COMPANY  
115 S 4TH ST  
ELMA WA 98541

|                |                    |                                |            |                       |            |
|----------------|--------------------|--------------------------------|------------|-----------------------|------------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | PROM. DATE | ESTIMATED<br>10-12-90 | VIA<br>UPS |
|----------------|--------------------|--------------------------------|------------|-----------------------|------------|

|               |     |           |     |             |       |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION:

☐

NEW

☐

SLIGHTLY WORN

☐

VERY WORN

☒

MISUSED

☐

MARRED

CUSTOMER'S REQUEST

*Gun goes off by itself*

MAIN FAULT

*Tugger assembly contaminated with sticky-gummy residue. Internal parts of tugger assembly not moving freely - rear safety cam & stuck to back plate of tugger assembly - as result, bolt cannot be inserted into action because of stuck rear safety cam. Rifle has not been properly maintained*

PARTS

*Send repair quotation for new tugger assembly at 1/2 normal price - the present assembly cannot be properly cleaned*

|                  |       |       |      |        |         |
|------------------|-------|-------|------|--------|---------|
| REPAIRMAN<br>RBA | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER   | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD5925 REV. 6