

Cust Comp

P.I. 110 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: GOOD R #: 020932
OUTSIDE WORK: BY ARDEN SPORTS UNLIMITED DATE: 10/13/72
SACRAMENTO, CAL. FROM: DENNY'S HOME.
FIRED AMMO TYPE: - ARBUCKLE, CAL.
& CONDITION: _____ GUN #: 6423856
PROOF: R.E.P. ASSEMBLER INSP.: 9 TEST: 87 CODE: AU = 3/71
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: G. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010
(MIN. IS .020) TRIGGER PULL SET TOO LIGHT.

COMPLAINT: SAFETY DOES NOT WORK.

INCIDENT: FOLLOW DOWN

COMMENTS: COMBINATION OF LIGHT TRIGGER PULL, UNDER
MIN. ENGAGEMENT AND TRIGGER BURRS, CAUSED
THE TRIGGER TO STAY IN FIRED POSITION RESULT
IN FOLLOW DOWN.