

bcc: E.F. Barrett
E.G. Larson
R.B. Sperling
J.E. Preiser
J.H. Chisnall
D.J. Sanita
R-02207

April 18, 1960

-2-

under the sear and, in this condition, on moving the safety to the "fire" position, the rifle will fire if the trigger is touched. In addition, as previously mentioned, the trigger guard has been bent and indications are that the trigger has been binding on it. This condition could have caused the trigger to hang-up resulting in an accidental discharge also.

The firearm can be returned as received, or, if you so desire and as a gesture of good will, we offer to replace the damaged trigger assembly (with bent trigger) and the damaged trigger guard, at no charge. We will await your decision and reply.

Thank you for having afforded us this opportunity to examine the rifle and to be of service.

Sincerely,

J.A. Stekl, Supervisor
Firearms Product Service

JAS:tpg