

Dennis unable To Duplicate 12/29
T.P. 17# / S.L. .006
Trig Has Been Adjusted Outside
Of Factory - No Force On Front Of
Connector Brown Residue Is
Evident On B. S. Release
Gun Condition Poor - Witness
The Rust - Charge For Replacement
→ Must