

RECEIVED BARBER KINZER PPS GAL RE0001462		COMMENTS: <i>STEEL</i>		ORDER NO: <i>R92713652</i>	
INITIALS: <i>EP</i>	CUSTOMER ORDER NO.	BBL NOT OF OUR MFG			
DATE RECEIVED: <i>06/22/92</i>	DATE OPENED: <i>06/23/92</i>	DATE CODE: <i>PV3 6-79</i>	SERIAL NUMBER: <i>6200976</i>	NEW SERIAL NUMBER	MODEL AND GRADE: <i>660 220S</i>
ACCESSORIES: <i>W/STUDS</i>		<i>W/1 SWIVEL</i>			
FROM: <i>DINUNZIO, WILLIAM PO BOX 1307 SOUTH STREAM ROAD BENNINGTON VT 05201</i>			SHIP TO: <i>DINUNZIO, WILLIAM PO BOX 1307 SOUTH STREAM ROAD BENNINGTON VT 05201</i>		
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		CUST NO: <i>038921 C.O.D</i>	
WRITE ☐		CLEAN/TEST		PROM. DATE	ESTIMATED: <i>7-7-92</i>
GUN CONDITION:		<i>bbl not our mfg</i>		VIA: <i>UPS</i>	
☒ NEW				REPAIR CHARGE	
☐ LIGHTLY WORN				EXCISE	
☐ WORN				TAX	
☐ VERY WORN				INSURANCE	
☐ UNREPAIRABLE				UPS	
☐ MARRED				PARCEL POST	
TOTAL					

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	<i>A1</i>	<i>B1</i>	<i>fires when safe is released</i>			
TRIGGER GROUP		<i>B2</i>				
BOLT ASSY		<i>B3</i>				
BARREL ASSY		<i>B4</i>				
REC. ASSY		<i>B5</i>				
WOOD			<i>C1</i>	<i>D3</i>	<i>E5</i>	<i>F5</i>
METAL			<i>C2</i>			

MAIN FAULT: *Cannot duplicate problem - rifle cannot be made to malfunction. However weight of pull adjustment has been altered outside factory (plant making pull adjustment screws) weight of pull measured at 8 1/2 pounds.*

Searif - 2012"

ARTS	COMMENTS: <i>We can either re-adjust present assembly to our specifications, or we can offer to install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if that will better restore confidence in the rifle.</i>				
REPAIRMAN: <i>ES</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE