

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 002678
OUTSIDE WORK: No DATE: 2-2-72
FROM: BILL DOTSON'S INC.
FIRED AMMO TYPE: - DECATUR, ILL.
& CONDITION: _____ GUN #: 6294075
PROOF: R.E.P.-A INSP.: 9 TEST: 13 CODE: XS = 12/69
HEADING: O.K. GA./CAL.: 270 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 6LBS., ENGAGEMENT .020. TRIGGER
BIND IS NOTICEABLE. IN DIS-ASSEMBLING THE TRIGGER
HAS WHAT APPEARS TO BE DRIED STEEL GUARD ON
THE SIDES CAUSING IT TO BIND.

COMPLAINT: "WHEN BOLT IS PUT IN ALL THE WAY THE GUN WILL
GO OFF!"

INCIDENT: FOLLOW DOWN

COMMENTS: THE SLUGGISH TRIGGER PROBABLY FAILED TO
RETRACT RESULTING IN A FOLLOW DOWN MALFUNCTION.