

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 93-27027

INITIAL JUM	CUSTOMER ORDER NO. 1735				
DATE RECEIVED 12/03/93	DATE OPENED 12/13/93	DATE CODE EV 10-79	SERIAL NUMBER A6838496	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMAG BDL
ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS					

FROM:

F. Duffy
DUFFY'S GUN ROOM
FALLS 7 BLACK ROCK ROADS
SPARKS MD 21152

SHIP TO:

DUFFY'S GUN ROOM
FALLS 7 BLACK ROCK ROADS
SPARKS MD 21152

CUST NO: 002317 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 1-7	VIA UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			25.0 EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Unable to duplicate customer concern. Examination of the 1979 rifle revealed, rust on action, trigger assembly and firing pin. Also action seemed stuck and firing pin study substance. For maintenance.

COMMENTS

Replace trigger assembly. Clean action, replace firing pin as 1/2 normal replacement cost. in future of good work.

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1