

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 92-21149

BARBER - Kinzer PPS GAL RE0001534

INITIAL CUSTOMER ORDER NO.

FPS 33145

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
10/07/92	10/13/92	0D 7-83	B6470503		700 30-06 BDL
ACCESSORIES		SCOPE BASE			

FROM:

SHIP TO:

DUNBARS GUN REPAIR INC  
509 1/2 UNION STREET  
SPARTANBURG SC 29301

DUNBARS GUN REPAIR INC  
509 1/2 UNION STREET  
SPARTANBURG SC 29301

CUST NO: 006084 ILTON L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION <input type="checkbox"/> NEW <input type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED						REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	release
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Sent to J Steel  
 Cannot duplicate complaint. However disassembly of trigger assembly and underneath receiver are covered with grey oil. Inside of trigger assembly contaminated with dirt and oil. Even in above condition, the rifle could not be made to malfunction.

Trigger pull 4.5 pounds; clean - lift a 0.11"

PARTS	COMMENTS
	1) Clean excessive oil off barrel of receiver
	2) After following operation: a) Clean & reassemble trigger assembly
	b) install new trigger assembly at normal cost, as a gesture of goodwill, if that will better our confidence in rifle
	3) Clean new trigger, guard assembly at normal cost, as goodwill gesture
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PAT	DATE

OFFICE COPY

RD6925 REV

BARBER - Kinzer PPS GAL RE0001534

PPS 01529